United States of America

Department of Transportation—Hederal Aviation Administration

Supplemental Type Certificate

Number

This certificate, issued to

Kosola and Associates, Inc. 5601 Newton Road Albany, GA 31707

Added Notes at Surrender: Future unsafe conditions existing in the

product can result in an airworthiness directive requiring correction of the unsafe condition before further flight. If there is no entity to comply with 14 CFR 21.99(a), Required design changes, the existence of an unsafe condition might result in permanently grounding of the aircraft.

Beplacement parts might not be available in the future

certifies that the ch	hange in th	e type i	lesign _y	for the	following	product wi	th the l	inziti	xifns	Janz	t conj	litions
								11		\sim	\/	

therefor as specified hereon meets the airworthiness requirements of Part

Street divil Air

Regulations.

Original Product - Type Certificate Number: A6WE

Make: McDonziell Douglas

Approval by: 74

Description of Type Design Change: Installation of the Fenwall Lavatory Smoke Detector System in accordance with Kosola Report KR-749, Rev. C, dated June 12, 1989, or later FAA approved

revision.

Limitations and Conditions? This approval should not be extended to other aircraft of this model on which other previously approved modifications are incorporated unless it is determined by the interrelationship between this change and any of those other previously approved modifications will introduce no adverse effect upon the airwortKines's of that airplane. Federal Aviation Administration approved Airplane Flight Manual\Supplement\dayted June 23, 1989, is a required part of this STC.

and the supporting data which is the basis for approval shall remain in effect until surnded, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration

Date of application:

November 1, 1988

Date reissued:

Date of issuance :

June 23, 1989

Date amended :



Acting Manager, Atlanta Aircraft

Certification Office (Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.